OFDA	POTENTIAL MATARRAIG			WASTE SIT		REGION	SITE NUMBER (to be se-	
POTENTIAL HAZARDOUS WASTE SITE IDENTIFICATION AND PRELIMINARY ASSESSMENT					VI			
NOTE: This form i								
submitted on this fo	NOTE: This form is completed for each potential hazardous waste site to help set priorities for site inspection. The information submitted on this form is based on available records and may be updated on subsequent forms as a result of additional inquiries and on-site inspections.							
GENERAL INSTRUCTIONS: Complete Sections I and III through. X as completely as possible before Section II (Preliminary Assessment). File this form in the Regional Hazardous Waste Log File and submit a copy to: U.S. Environmental Protection Agency; Site Tracking System; Hazardous Waste Enforcement Task Force (EN-338); 401 M St., SW; Washington, DC 20460.								
I. SITE IDENTIFICATION TXDOD 80 89021								
KOPPERS COMPANY, Organic Materials Div. B. STREET (or other Identifier) P. 0. Box 9746 (12700 Industrial Rd.)								
Houston, (Ga				TX	77015	Harris		
G. OWNER/OPERATO						12. TELE	PHONE NUMBER	
Mr. Al	Carnes, Pla	ant Engine	er			(713)4	(713)453-5446	
H. TYPE OF OWNERS	HIP				•	<u> </u>		
1. FEDERAL 2. STATE 3. COUNTY 4. MUNICIPAL X S. PRIVATE 6. UNKNOWN								
i. SITE DESCRIPTION This plant produces industrial pitches (carbon binder pitch) coal tar enamel, roofing bitumens, creosote, and creosote solutions.								
J. HOW IDENTIFIED (i.e., citizen's comp	lainte, OSHA ci	tations, etc.)				K. DATE IDENTIFIED	
Eckhart List	Eckhart List, EPA Region VI, (TX394/6) 11/20/79							
L. PRINCIPAL STATE	CONTACT							
Mr. Clarence Johnson, TDWR District 7						(713	3)479-5981	
			Y ASSESSME	NT (complete, t	hie eection last)		\$110cm-us	
1. HIGH	S. MEDIUM		4. NONE	□ 8. t	INKNOWN		SUPERFUND FILE	
B. RECOMMENDATION	1				 		DEC 2 3 1991	
1. NO ACTION NEEDED (no hazard) 2. IMMEDIATE SITE INSPECTION NEEDED 3. TENTATIVELY SCHEDULED FOR:						DED		
1. SITE INSPECTION NEEDED					REORGANIZE			
A. TENTATIVELY SCHEDULED FOR: b. WILL SE PERFORMED BY:								
b. WILL BE PERFORMED BY:								
4. SITE INSPECTION NEEDED (low priority)								
C. PREPARER INFOR	MATION //							
C. PREPARER INFOR		2. TELEPHONE NUMBER			8. DATE (mo., day, & ym)			
				(214)742-4522			Sept. 22, 1980	
III. SITE INFORMATION A. SITE STATUS								
1. ACTIVE (Those municipal sites which for waste treatment, at en a continuing basis, quently.)	are being used torage, or disposal	2. INACTI	VE (Those longer reseive	3. OTHER (epecify): (Those sites that include such incidents like "midnight dissoling" where no regular or continuing was of the site for waste disposal has occurred.)				
B. IS GENERATOR ON	SITET	L	····	<u></u>				

X 2. YES (apocity generator's four-digit gic Code): 2865, 2952

b. IF APPARENT SERIOUSNESS OF SITE IS HIGH, SPECIFY COORDINATES

1. LATITUDE (deg.-min-eec.)

2. LONGITUDE (deg.-min-eec.)

Z 2. YES (specity): 6 buildings that constitute manufacturing facility.

Continue On Reverse

☐ 1. NO

C. AREA OF SITE (IR eares)

🔲 1. NO

E. ARE THERE BUILDINGS ON THE SITE!

. ...

Continued From Front								
			VII, PERMIT INFO	RMATION				
A. INDICATE ALL APPLICABLE PERMITS HELD BY THE SITE.								
X 1. NPDES PERMIT Z. SPCC PLAN			IX 3. STATE PERMIT(epocify): Solid waste Reg. # 31386					
4. AIR PERMITS			6. ACRA TRANSPORTER					
			9. RCRA DISPOSER					
10. OTHER (epocity)	:							
B. IN COMPLIANCE?								
🔲 I. YES	[X 2. NO	3. UNKNOWN						
4. WITH RESPECT TO (Het regulation same & sumber): State Water Quality Permit 01034								
		V	III. PAST REGULATO	RY ACTIONS				
A. NONE								
See attached notes.								
see attached i	ioces.							
IX. INSPECTION ACTIVITY (past or en-toing)								
A. NONE	A. NONE (complete from: 1,2,3, & 4 below)							
1. TYPE OF ACTIVITY PAST AC		PAST ACTIO	ON 64:	4. DESCRIPTION				
Ongoing Inspection		present	date State -	TDWR - see notes*				
<u> </u>		X. (REMEDIAL ACTIVITY	(past or en-foing)				
A. NONE								
1. TYPE OF ACTIVITY PAST ACTI		2. DATE OF PAST ACTIO (mo., day, &)	S. PERFORMED	4. DESCRIPTION				
		TDWR	Mr. Clarenc	e Johnson, Deer Park, TX				
NOTE: Based on the information in Sections III through X, fill out the Preliminary Assessment (Section II) information on the first page of this form.								

*Long sleeves, hard hat, and safety glasses required to enter plant.

V. WASTE RELATED INFORMATION (continued)
3. LIST SUBSTANCES OF GREATEST CONCERN WHICH MAY BE ON THE SITE (place in descending order of hazard).

Other polynuclear aromatic hydrocarbons - pyrene, fluoranthrene, 3, 4 benzpyrene, napthalene & biphenyl.

4. ADDITIONAL COMMENTS OR NARRATIVE DESCRIPTION OF SITUATION KNOWN OR REPORTED TO EXIST AT THE SITE.

VI. HAZARD DESCRIPTION							
A. TYPE OF HAZARD	POTEN- TIAL HAZARD (mark 'X')	C. ALLEGED INCIDENT (mark 'X')	D. DATE OF INCIDENT (mo.,day,yn)	E. REMARKS			
1. NO HAZARD		28836999	SAME STATES	10个年间,但如此的第三个部分的特别的。			
8. HUMAN HEALTH)					
s. NON-WORKER INJURY/EXPOSURE							
4. WORKER INJURY							
S. CONTAMINATION OF WATER SUPPLY	х			See attached notes.			
C. CONTAMINATION FOOD CHAIN							
7. CONTAMINATION OF GROUND WATER							
S. CONTAMINATION S. OF SURFACE WAYER							
g. DAMAGE TO FLORA/FAUNA							
16. FISH KILL	Х			See attached notes.			
11. CONTAMINATION							
12. NOTICEABLE GOORS							
18. CONTAMINATION OF SOIL	<u> </u>						
14. PROPERTY DAMAGE							
15. FIRE OR EXPLOSION							
16. SPILLS/LEAKING CONTAINERS/ RUNOPP/STANDING LIQUIDS							
17. SEWER, STORM DRAIN PROBLEMS							
ts. Erosion ProsLEMS							
18. INADEQUATE SECURITY	,						
20. INCOMPATIBLE WASTES			1				
E1. MIDNIGHT DUMPING							
ES. OTHER (specify):				,			



TEXAS WATER COMMISSION Stephen F. Austin State Office Building Austin, Texas

PERMIT TO DISPOSE OF WASTES
under provisions of Chapter 26
of the Texas Water Code

brug Otheren

01034

This permit is a renewal of Permit No. 01034 (approved January 2, 1979)

NPBES PERMIT NO. TX 0005096

PERMIT NO.

(Corresponds to

Koppers Company, Inc.

whose mailing address is

P. O. Box 9746 Houston, Texas 77015 SUPERFUND FILE

DEC 23 1991

REORGANIZED

is authorized to dispose of wastes from a facility which produces industrial and roofing pitch and creosote (SIC 2865)

located east of Federal Road, south of Old Industrial Road and adjacent to the Armco Steel Plant, Galena Park, Harris County, Texas

to the Amerada Hess drainage ditch; thence to the Armco Steel drainage ditch; thence to the Houston Ship Channel (Segment 1006) in the San Jacinto River Basin

in accordance with effluent limitations, monitoring requirements and other conditions set forth herein. This permit is granted subject to the rules of the Department, the laws of the State of Texas, and other orders of the Commission.

This permit and the authorizations contained herein shall expire at midnight, March 31, 1982.

APPROVED, ISSUED, AND EFFECTIVE this 30th day of June 19 80.

ATTEST: Mary how stepper Sel. M. Downs

ROPPERS COMPANY, INCORPORATED
P. O. Box 9746
Houston, Texas

OPPESSE TATE	BOTIGE DATE	O. REPLY DATE	violaticks	* 1
1.26.23	8 10.75	8-13-73	Phenel	· · · · · · · · · · · · · · · · · · ·
1-6-75	1-17-75	1-21-75		
6-3-75	8-19-05	1:5	Tic	• • • • • • • • • • • • • • • • • • • •
6-3-25	6-25-78	1-2-05	Toc.	
7-5-75	30105	7-23-75 He	TCC, Tion	,
9-17-75	4-26-05	10-5-15	Gerakara	y toxic was
11-4-05	12-3-25	12-12-25	Toc.	y a ta was
11-20-05	1-9-26	1.19-06	TOC, Cyan	ide
2-4-76	2-16-26	2-25-16	TOC, AX	• •
• · · · · · · · · · · · · · · · · · · ·	•		, ·	

SUPERFUND FILE

DEC 2 3 1991

REORGANIZED